



Micron Technology, Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United States

Micron Standard Master Container Box Label Changes

PCN: 32897

Published: 2019-08-28

Type:	Shipping Labels Change	
Description:	Micron is removing the 4S label and is also removing the mailing label from Master Container Boxes (MCBs) to reduce redundant information and align with customer requirements to use fewer labels. The mailing label removal will be applicable only when shipments are made using FedEx . Changes with additional carriers (UPS, DHL) will be made at a later date when systems are capable of supporting. In addition, barcodes will be added to the Packing List. See attached for details.	
Reason:	Better Align With Industry Standard	
Product Affected:	All Micron Products	
Affected Micron Part Number	Recommended Replacement	Customer Part Number
	*Materials that have been ordered are in bold .	
Method of Identification:	Label changes. Barcodes will be visible on packing list	
Micron Sites Affected:	All Sites	
Product Ship Date:	2019-09-27	

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Micron Standard Master Container Box (MCB) Label Change

©2018 Micron Technology, Inc. All rights reserved. Information, products, and/or specifications are subject to change without notice. All information is provided on an "AS IS" basis without warranties of any kind. Statements regarding products, including regarding their features, availability, functionality, or compatibility, are provided for informational purposes only and do not modify the warranty, if any, applicable to any product. Drawings may not be to scale. Micron, the Micron logo, and all other Micron trademarks are the property of Micron Technology, Inc. All other trademarks are the property of their respective owners.




Reason for change:

To reduce number of labels

- Micron is removing the 4S label and the Mailing label from Master Container Boxes (MCBs) to reduce redundant information and to *align with customer requirements to use fewer labels*.
- The Mailing label removal is applicable only when shipments are made using FedEx.
- Mailing label changes with additional carriers (UPS and DHL) will be made in Spring 2020 when systems are capable of supporting.

Micron Standard Master Container Box (MCB) Label Change

- There are only three minor differences between the 4S and 3S labels. These differences are indicated below:



Micron Standard Master Container Box (MCB) Label Change

- There are only three minor differences between the Mailing and Carrier (Courier Waybill) labels. These differences are indicated below:

Mailing Label

Micron Technology, Inc.
1160 Exchange, Dock 1D
BOISE ID 83716
USA

US01

Micron Semiconductor (Xian) Co., Ltd
Zone B Shaanxi Xian EPZ
Xinxi Avenue, Gaoxin District
710119 XIAN
CHINA

WB # 668224775312 / 0417498968
Child W/B: 668224775334

Piece 3 of 3

PO #s

PKG ID: 417498968A3

Mailing	
WB# and Child W/B	
Piece	
PO#s	
Carrier	
	HAWB
	Package Count
	Consol

Carrier (Courier Waybill)

Shipper
Micron Semiconductor Xian Co. LTD.
Zone B of Shaanxi Xian EPZ
Xinxi Avenue, Gaoxin District
USCI#91610131717866266H
710119 XIAN
CHINA

Ship-to

Forwarder
Micron Semiconductor Xian Co. LTD.
Zone B of Shaanxi Xian EPZ
Xinxi Avenue, Gaoxin District
USCI#91610131717866266H
710119 XIAN
CHINA

Intermediate Consignee

HAWB: 668119124666

Package ID: 420061325A1

Consol:

Package Count: 1 of 1

Micron's Standard Master Container Box (MCB) Label Change

Once this change is completed, the number of labels will be reduced on an MCB from four to two.

MCB Labeling Example

Color Scheme:

Yellow – Current labels

Red – Labels to be removed

Magenta – Optional label

